

PCN #: WE100728MP

Date: Aug 17, 2010

Re: PFC MegaPAC Fan Guard

To Our Valued Customers

We appreciate your use of Westcor's PFC MegaPACs. This notice is to inform you of a change to the product fan guard

PCN Type:

Notice of a change in product appearance

Product(s) Affected:

PFC MegaPAC, PFC MegaPAC-EL, PFC MegaPAC-HP, PFC MegaPAC-HPEL,

Proposed Change:

Replace existing plastic fan guard with nickel plated steel guard

Reason(s) for the Change:

Improved durability. The existing plastic guard is easier to damage with improper handling, and when damaged may require product return to the factory due to the method used to attach the cover, guard, and fan



Plastic Fan Guard



New Steel Guard

Validation Data:

The new guards have been evaluated for safety, security and airflow impact, as well as going through normal factory processing as part of completed units. No performance changes were noted. No impact to RoHS status



PCN – PRODUCT CHANGE NOTICE PAGE 2 OF 2

Customer impact:

Any changes to external dimensions are negligible. Since Westcor requires 2 inches free space behind the fan opening to ensure proper airflow there will be no impact to any mounting or handling requirements

Effective date of change:

The new fan guard will start shipping with the affected product lines approximately 9/1/2010

Company Contact:

Jeff Lally
Westcor Marketing
Westcor Division of Vicor
560 Oakmead Parkway
Sunnyvale, Ca. 94085-4022
jlally@vicr.com